STAT

Sanitized Copy Approved for Release 2010/10/18 : CIA-RDP87-00031R000100040010-9



Sanitized Copy Approved for Release 2010/10/18: CIA-RDP87-00031R000100040010-9

Sanitized Copy Approved for Release 2010/10/18: CIA-RDP87-00031R000100040010-9

TRÂNSMITTAL SLIP

TO:

C/PEPS

ROOM NO. BUILDING
2F31

REMARKS:

FROM: OL Safety Officer

ROOM NO. BUILDING

EXTENSION

FORM NO. BUILDING

FORM NO. BUILDING

FORM NO. BUILDING

FORM NO. BUILDING

FORM NO. 241

REPLACES FORM 38-8
WHICH MAY BE USED. (47)

STAT

STAT

Sanitized Copy Approved for Release 2010/10/18: CIA-RDP87-00031R000100040010-9



## VISORY NEWS

March 16, 1983

SAFETY ALERT

Two recent incidents have uncovered a previously unknown phenomenon of serious gravity.

At Dequesne Electric Company a worker threw an electrical power switch into closed position which produced a short-lived sparking.

An employee, at UFS, flipped open the colored lense of his welding goggles to better position the welding rod. He inadvertantly struck the metal to be welded, producing an arc.

Both men wers wearing contact leases. On returning home from work, they removed the concact; and the cornea of the eye was removed along with the lease.

RESULT: Permanent blindness!

The electrical are generates microwaves that instantly dries up the fluid between the eye and the lense, causing the cornea to be bonded to the lense. This trauma is painless and the individual never knows an injury has occurred until removing the contacts.

Federal and state safety and health agencies are investigating these situations and will respond according to their findings.

With this in mind, it is suggested that no contact lenses he worn by anyone who is potentially subject to an electrical sparking situation.

Copy Approved for Release 2010/10/18: